



## Emergency Levee Repairs

### Location

River: Cache Creek

Levee Mile: 1.1

Latitude/Longitude:

38.721995/-121.807970

Nearest Impact Area:

Woodland

County: Yolo

Bank: Left

### Type of Damage

Bank erosion

### Length of Repair

860 feet (approximate)

### Repair Type

Setback levee

### Lead Agency

Department of Water Resources

For further information,  
please contact:

**Elizabeth Scott**  
**DWR Public Affairs Office**  
**(916) 835-5344**  
**[leveerepair@water.ca.gov](mailto:leveerepair@water.ca.gov)**

DEPARTMENT OF WATER RESOURCES  
PO Box 942836, Sacramento, CA 94236

**[www.levees.water.ca.gov](http://www.levees.water.ca.gov)**

